

Anzugsdrehmomente ZERAMEX® VICARBO® Schrauben



System ZERAMEX® P6

 <p>P15450</p> <p>Anzugsdrehmoment: 25Ncm</p>	 <p>P15451</p> <p>Anzugsdrehmoment: 25Ncm</p>	 <p>P35550</p> <p>Anzugsdrehmoment: 15Ncm</p>
 <p>P16450</p> <p>Anzugsdrehmoment: 35Ncm</p>	 <p>P16451</p> <p>Anzugsdrehmoment: 35Ncm</p>	 <p>P36550</p> <p>Anzugsdrehmoment: 15Ncm</p>

System ZERAMEX® XT

 <p>RB16550</p> <p>Anzugsdrehmoment: 25Ncm</p>	 <p>RB36553</p> <p>Anzugsdrehmoment: 5Ncm</p>	 <p>P36550</p> <p>Anzugsdrehmoment: 15Ncm</p>
---	--	--